

Article no.: M-2559



Product data:
**Behälter 20.000 Liter aus V2A isoliert,
gebraucht,
Standing**

EUR 17.200,00

zzgl. 19 % MwSt. excl. shipping

in stock: 1

Location: 33378 Rheda-Wiedenbrück

Behälter 20.000 Liter aus V2A isoliert, gebraucht consists of the material 1.4301(AISI304) V2A. The volume is approx. 20,000 litres. The diameter inside includes 2200 mm.

Behälter 20.000 Liter aus V2A isoliert, gebraucht was last used in the following area: Foodstuffs.

1 pieces of Behälter 20.000 Liter aus V2A isoliert, gebraucht is/are currently still available. Delivery can take place worldwide.

Product description

General

Material in contact with product 1.4301(AISI304) V2A

Volume approx. 20,000 litres

Structure Standing

DIN design unknown

Year of manufacture 1989

Manufacturer Thrun

Condition Used

Dimensions approx.

Internal diameter 2200 mm
External diameter 2360 mm
Cyl. height 5260 mm
Total height 7550 mm
Wall thickness of product chamber head 2,50 mm
Wall thickness of product chamber shell 2,50 mm
Wall thickness of product chamber floor 2,50 mm

Design

Weight approx. 2500 kg
Weight per unit volume approx. 1000 kg/m³
Insulation No
Insulated area Shell and floor
Insulation cladding Fully welded stainless steel
Insulating material Polystyrene
Interior surface Smoothed
Exterior surface Smoothed
Floor type Conical bottom
Head design Conical bottom
Product chamber operating pressure Atmospheric/unpressurised

Equipment

Temperature-controllable No

Agitator

Agitator quantity 1 (piece)
Agitator position Head off-centre
Agitator type Propeller
Note on agitator Welle bodengelagert
Agitator - Voltage 380/660 V
Agitator - Output 2,2 kW

Supports

Supports Stainless steel feet

Number of feet 3 (piece)

Note on supports höhenverstellbar

Fixtures and fittings

Mannloch 1 Größe 400 DN mm

Manway position In head

Outlet nozzle 65

Cleaning/CIP nozzle in head

Fixtures and fittings Lifting lugs
Sample taking

Additional fixtures and fittings Air vent, Nameplate,

Other notices


Technical documentation Designation

Comment on technical documentation Rührwerkspos. in der Zeichnung abweichend

Note in der Zeichnung ist die R $\frac{1}{4}$ hrwerksposition falsch
eingetragen. Vorhandene K $\frac{1}{4}$ lmantel defekt.

Last usage Foodstuffs

Pictures





Terms and conditions

The general terms and conditions of Georg Heuer Behälterhandel und Industriebedarf GmbH apply. [View here.](#)